G. R. S. 59] GPB—15,000—20 12 13

GENERAL AND REVENUE SECRETARIAT.

1895-96
191
(Miscl)

File No. 24

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Sanctioning an Estimate for Rs 682/- for repairing the Govt Chattram at Bidadi Chennapatna Taluk

PREVIOUS REFERENCES LATER REFERENCES

Mang. F. 24 Genl. Serial No. 80

1895

MUZARAI.

From

To The Dy Commr
Bangalore Dist

Dated 19 July 1895

Despatched 20

Received

Enclosures No.

General No. 85 A
Muzarai F. No.

Has the honor to request that Treasury officer's certificate shewing the amount of Surplus funds now available at the credit of the Govt Chattram at Bidadi, Channapatna Taluk, may be forwarded to this office at an early date.

By order
A
for Secretary

To the Same No 2369/12-8-95
From the Same No 1916/21-8-95

Gen. Serial No. 31.]

160

189

From

The Deputy Commissioner
Bangalore District.

To

The Secretary to the
Government
~~Durbar~~ of Mysore.
Mungaroi Department.

Dated 21st August 1895

Despatched 22nd Do

Received 26/8

Enclosures—No. 3,

General No.
No. 196.

Mungaroi
Secretary's docket No. 85
dated 20th Ultimo.

Order no: dated 26-8-95

issued
HS
26/8/95

As requested in the above, has the honor to submit, herewith, the Taluk Treasury Officer's Certificate, together with the Amildar's report, shewing the amount of surplus funds now-

To the Sanads 390-1 & 11-9-95

available at the credit
of the Government
Cluttram at Bidadi,
Channapatna Taluk,
as called for in the
above.-

K Chandy

for Deputy Commissioner

Read

Docket No 196
dated 21st Augt 95
from the Dy Commr
Bangalore District
reporting that a Sur-
plus fund of Rs. 159-13-
is now available at
the credit of the Govt
Chattram at Bidadi
Channapatna Taluk
and that a sum of
Rs. 717-3-5 belonging
to the same Chattram
is deposited in the
Govt Savings' Bank.

R

No 390-1911-9-95
Ten 14 file V.P.41

Order thereon -

The Muzrai Supdt
during his late in-
spection found that
the Govt Chattram
at Bidadi was in
need of urgent re-
pairs and therefore
gave personal -

personal instructions for their immediate execution.

2. The estimate prepared by the overseer, Mudgal Deputy for carrying out the urgent repairs of the aforesaid Chattram amounting to Rs. 682/ is sanctioned, the charge being met from the sum of Rs. 717-3-5 deposited in the Govt Savings Bank.

3. The said overseer who is now in charge of the work should complete the repairs and submit a completion report to Govt in the Mudgal Deputy at an early date.

Secretary
6.V.

To Study Commr Bangalore Dist with a copy of the abstract estimate and Tracings.

" Comptroller, Mysore Govt with a copy of the abstract estimate.

Secretary's Office 22 Dec 95-6

Abstract

Quantity	Particulars	Per	Rate	Cost
52.6	Shifting tiles	Sqr	4 8	237
	Tile Slate for Valleys (Fixing)	Rft	- 12	53
8	Putting new Ventilator in Store (Teak)	Set	1 8	9.
32½	Putting new Window Shutters (Teak)	Set	1 -	32
34½	Putting new Door Shutters (Honney)	"	- 12	26
52½	—Do— (Jungle) -	"	- 8	26
3¼	Wood work (Teak)	Cft	3 8	11
16	Fixing (Honney)	in	2 -	32
50½	Iron bars for the Bath Room	lb	- 2	6
78	Constructing Brick in Chunam walls for the Bath Room	Cft	- 3	15
60¾	Roofing with Tile slate for Bath Room	Sqr	- 6	23
1·32	Chunam plastering do walls	Sqr	2 8	3
220	Constructing Brick in mud walls for Stables	Cft	- 1 6	21
2·30	Putting Concrete & plastering over it in the Drawing Room & Store	Sqr	2 8	6
3·83	Gravel flooring for the Stables	Sqr	1	4
2·82	Chunam plastering for Stable walls	"	2 8	6
39¾	Putting Stone Slabs for the water closet	Sqr	3	7
52	Putting Eave Board for front Verandah	Rft	2 -	7
	Petty Repairs			
2	Putting Stone benches in the Store	each	5 -	10
1	hanging lamp in the Hotte		3 8	3
	Repairing the floor of the whole building	Rs.		5
1	Putting one lamp post with lantern	each	5 -	5
4	Cooly for putting of old beams.	each	1	4
	clearing the Site.	Rs		5
3	Repairing the Crack —	each	1 8	4
		Carried over		44

	Brought forward—					560
	White washing	Sqr				24
71	wood oiling (2 coats) outside of the small Verandah in front of Kitchen behind	"	5			4
40	Iron bars	Wt	0	2		5
2	Teak wood work	Cft	3	8		7
24	Zinc flat	Sft		6		9
	Fixing the Verandah with nails complete	LS.				5
23	Constructing Brick in Chunam walls for raising the walls of Bath Room	Cft		8		4
4·90	wood oiling (1 coat Inside)	Sqr	3			15
128	Coping for the front Verandah,	Rft		1	6	12
	Putting 1 Board near the Kalyani for prevent from people washing their clothes and committing nuisance in the Kalyani	LS.				5
		Total Rupees				650
	6th Sept. 95 Bangalore	Contingencies at 5%				32
		Grand Total Rupees				682

Rupees Six hundred and eighty two only Balakrishna N.

Gen. Serial No. 31.] 351

1895-96.

OFFICE OF ... GRANT ... VANCE M'S'C

From The Dy Commissioner,
Bangalore District

To

The Secretary to the Govt.
~~Durbar~~ of Mysore.
Muzrai Department.

Dated 24th October 1895.
Despatched 25th Do
Received 28/10

Enclosures—No. 1

General No.
D No. 385

Has the honor to forward, herewith, Extract from the Government Proceedings No 390-1 Dated 10th September last, Regarding the urgent Repairs to be carried out to the Government Chattram at Bidadi, Closepet Sub Taluk, and to request that the same may be delivered to the Overseer, Muzrai Department for his information and guidance

K Lawdy
for Dy Commissioner.

To the Sanction 600 24-95 of 15-11-95

Proceedings of the Government
of Mysore.

Read Docket No. 196 dated 21st August 1895 from the Dy Commissioner, Bangalore District.

× × × ×

Order thereon No. 390-1 dated 10th September 1895.

× × × ×

2. The estimate prepared by the Overseer, Muzrai Department, for carrying out the urgent repairs of the Government Chattram at Bidadi, Channapatna Talukh, amounting to Rs 682/. is sanctioned, the charge being met from the sum of Rs 717-3-5 deposited in the Government Savings Bank.

3 The said Overseer who is now in charge of the work

should complete the repairs and submit a completion report to Government in the Mazra'i Department, at an early date.

(Signed) A. Stevenson Charlu
Secretary

"Extract"

V. Chaudhry
In Dy Commissioner

Gen. Serial No. 30.]

1895

MUZARAL

From

To The Dy Commr
Bangalore Dist

Dated 15th

Despatched November 1895

Received

Enclosures No. 1

General No. 600 B
Muzarai F. No. 24-95

His No. 385 of the 24th ult
Ultimo forwarding for
delivery to the overseer
Muzrai Deptt an extract
from the Govt Proc. No.
390-1 dated 11th Sept 95
regarding the urgent repairs
to be executed to the Govt
Chattram at Bidadi
Channapatna Taluk.

With reference to the
above has the honor to

to forward herewith for information report dated 14th Novr. 193- from overseer, Ozala -Krishna Rao, shewing that the work is in rapid progress and that the same will be completed within a week.

After the work is completed, a bill of actual cost will be forwarded to the Dy Commr. for payment from the sum of Rs 717-3-3 belonging to the Chattram and deposited in the Govt. Savings Bank.

By Order

Secretary.

Gen. 31]

1895-96.

From The Dy Commissioner,
Bangalore District.

To The Secretary to the
Government of Mysore
Muzrai Department.

Dated 9th January 1896.
Despatched 10th Do
Received

General No
D No. 645.

Enclosure No. 24.

Has the honour to forward, herewith, for favor of perusal, Urzee No. 45 of the 2nd Instant, from the Amildar of Chennapatna, bringing to notice that the bamboos used in the Repair of the Chattram at Bidadi are all old and rotten by the attack of insects and need to be replaced by new and mature ones.

if the repairs are to
last for any length
of time.

2. The items of work
not mentioned in the
enclosure to the Auditor's
Wrtee are not yet executed.

For Dy Commissioner,

Ejercicios de

[illegible]

Abstract Estimate Showing the probable cost of Repairing the Government Hotel at Bikeda

Quantity	Description of work.	Per	Rate			Cost
70	Zinc plate for valleys (fixing)	Sft	-	12	u	52
5 1/2	Putting new ventilator in Store/Teak	Sft	1	8	u	8
32 1/2	Putting new window shutters — /do u	do	1	u	u	32
34 1/2	do u New door Shutters (Hannay)	-	u	12	u	26.
52 -	— do u Jungle ——	-	-	8	u	26
50 1/2	Iron bars for the Bath room	lbs	-	2	u	6
78	Reconstructing Brick in Chunnam walls for the Bath Room — —	Sft	u	3	u	15
60 3/4	Roofing with Zinc plate for do u —	Sft	u	6	u	23
1.32	Chunnam plastering for Bath room	Sqr	2	8	u	3
180	Reconstructing walls, Brick in Mud for Stable	Cft	u	1	6	17
2-30	Concrete and plastering for the Drawing Room and Store Rooms ——	Sq.	2	8	u	6
3.83	Gravel flooring for the Stables	Sqr	1	u	u	4
2-15	Chunnam plastering for do u —	Sqr	2	8	0	5
54	Eve board for the front Verandah	Rft	u	2	u	7
no: 2	Putting Store benches in the Store ——	Each	5	u	u	10
L.S.	Plastering hooks, whole Building.	L.S	—	—	—	5
no: 1	Lamp post with Lantern ——	L.S	5	u	u	5
no: 4	Labour for fixing old beams —	Each	1	u	u	4
3	Repairing the Cracks —— ——	Sqr	1	8	u	4
96-11	Whitewashing —— —— —— Cancelled Verandah near Kitchen	Sqr	u	4	u	24
40	Iron bars -	lbs	u	2	u	5
13	Zinc plate	Sft	u	6	u	5
L.S	Fixing and nailing for Above —	L.S	.	.	.	5
23.	Reconstructing water brick in chunnam for raising the Store wall for the bath room	Cft	-	3	u	4
128	Coping for the front Verandah —	Rft	u	1	6	12
1	Wood work —— —— ——	Sft	3	8	0	3
52-65	Shifting tiles - - - -	Sqr	4	8	0	237
	Total Rupees					553

Assistant Engineer

Report on the repairs of the Government Chattram at Bidadi

The chattram was in a very bad condition leaking in many places, walls being cracked in 3 or 4 places, beams and bamboos eaten by white ants and the tiles on the top being broken. There were some doors and windows without either frame or shutters. The chattram was in want of a bath room very badly and some more improvements were necessary. To the above repairs and improvements an estimate at a cost of Rs 682 was prepared as per personal orders of the Mysore Secretary during his inspection of the Chattr

Accordingly the estimate was duly sanctioned The work was put in hand at once and the work being taken by the contractor Appajaya of the same place.

When most of the works were completed, it was inspected by the Murrai Secretary After which the amildar reported that some of the bamboos used were not good.

And now all the bamboos that were bad have been newly replaced by good and strong ones. and all the works have been executed which are satisfactorily done.

The accompanying completion bill for Rs. 608-1-0 with the measurement list will show the details of works done to the said chattram.

Balakrishna Rao

Muz overseer.

16th May 26

Measurement of work done for Repairing the Government Chattrum at Bidadi

Details	No	Measurement			Contents	Total
Shifting the tiles of the main building						
Front side	1	$\frac{52+41+52}{3}$		17	850	
Rear Side	1	$\frac{41+13\frac{1}{2}}{2}$		16	436	
Inside the thotte and Rooms	2	$\frac{42+46}{2}$		16	896	
outside — do —	1	$\frac{48+42}{2}$		7	315	
— do — with Rooms & a portion of a kitchen	1	$\frac{74+62}{2}$		7	476	
Rear Verandah in thotte.	1	$\frac{31+46}{2}$		11	248	
Front & rear side in kitchen	2	$\frac{53+41}{2}$		7	658	
Verandah in kitchen	1	39	10	.	390	
a portion between Kitchen & main building	1	28	7	.	196	
Stables	2	40	10	.	800	
Total sqrs						52.65
3" fine plate for Valleys.						
Sides in thotte	2	18	.	.	36	
— Do —	2	14	—	-	28	
Kitchen	1	6	.	.	6	
Total R ft						70
Ventilator in Store (Teak woodwork)	1	3	-	2	6	
Total sft						6

Teak wood Window Shutters only.

Drawing & Room & 2 Kitchens	6	3	1¼	-	22½	
Big kitchen	2	4	1¼	-	10	
Total Sft						32½
Honney' Shutters for Store & D.K.	2	5¾	3	-	34½	
Total Sq ft						34½
Jungle wood doors Big kitchen	1	6	3	-	18	
Small Kitchen & Store	2	5¾	3	-	34½	
Total Sft						52½

Wood work

Teak Bressummer for thatte	1	6½	6"	6½"	1½
Window frame in Drawing Room	1	4½	4"	4"	½
Door frame for the Entrance	1	7	4½"	4½"	1
Total c ft					3
Honney's jungle. Teh Rafters —	1	14	5½"	6"	3
— Do —	1	14	6"	7"	4
Rafters	2	10	4"	4½"	2½
— Do —	1	11	4"	4½"	1½
Bressummer	1	8	6"	6½"	2
Door frame for the top of Entrance door	1	5	4½	6"	1
Door frame in kitchen	2	4	4"	4½"	1
Bodega' —	2	3	4"	6"	1
Total c ft					16
Iron bars for the bath room —	2	16½	¾"	¾"	21/16x16
— Do —	1	6	¾"	¾"	6/16x16
27/16x16 x480/15 = 8-					27/16x16
Total Wt					50½

in Chunam walls for the bath room	1	7¼	¼	6¾	61	
Do —	1	4½	8	¼	17	
Total cft						78
roofing with Line plate.	3	9	2½	-	60¾	
Total Sft						60¾
Chunam plastering for bath room.	2	7½	7	.	105	
	2	4½	8	-	27	
Total Sqrs						1·32
Parapet wall for the Stables with foundation						
Front Side Brick in mud -	1	13	4	1½	78	
Cross — — Do —	1	11¼	4	1½	67	
Side — Do —	1	12½	4	1½	75	
Total cft						220
Chunam plastering both Sides	1	36	7		252	
Total Sqrs						2·52
Gravel flooring for the Stables	1	11½	26	-	299	
— Do —	1	12	7	-	84	
Total Sqrs						3·83
& concrete flooring for the Drawing room	1	13	9	-	117	
— Do — Store Room	1	12⅓	9	—	113	
Total Sqrs						2·30
Water closet for kalyani —						
Stone Slabs Floor	1	7½	2½	-	18¾	
Sides.	2	5	½	—	15	
— Do —	2	2	½	—	6	
Total Sft						39¾.
Eave board for the main building in the front Verandah						
Total Rft						54.
Wood oiling Eave board	1	54	⅓	—	28	
Pillars	4	5⅓	2	-	44	
Total Sqrs						71

Constructing a small Verandah in the front of Rear Kitchen room						
Frame with iron bars bolts nuts &c complete with 2 iron plate on the top & fixing	1	2 3/4	4	-	11	
Total Sft						
Raising the bath room wall	1	3 1/2	1 1/2	4 1/2	19 3/4	
Total Cft						19 3/4
Copeing for the top of the main front Verandah	8	16	-	-	128	
Total Rft						128
Petty Repairs.						
(1) putting 2 Stone benches in the Store						2
(2) keeping / hanging lamp in the Hotte						1
(3) Putting lamp post with lantern in the Hotte						1
(4) Repairing the floor of the Hotte & the walls of well & ~~some cracks~~						25.
(5) The labour for putting beams out of the old ones that were available at the Chatrum						4
(6) Clearing the site						2.5
(7) Repairing the cracks. by plastering and Cocking &c						3
Whitewashing & Outside the Hotte.	1	143	-	10 1/2	1455	
Drawing Room	1	50	-	11	550	
old Store	1	30	-	11	330	
Kitchen	1	30	-	11	330	
Rear of the Hotte	1	40	-	12	480	
Kitchen	1	40	-	10	400	
Verandah in front of Kitchen	1	55	-	9 1/2	522	
Dressing Room	1	88	-	11	968	
front passage	1	56 1/2	-	11	622	
Verandah	1	49	-	9 3/4	478	
— do — walls	2	11	—	7 1/2	165	
outside (all round)	1	191	—	12	2292	
Sables —	14	9 1/2	-	2 1/2	299	
Stables —	1	90	—	8	720	
Total Sqrs						96.21

Conservation Bell

Abstract of Measurement Book for Repairing the Government Cattrem at Bida &c

Sub-Heads.	Previous Measurements		Present.				Total up to date	
	Qy.	Cost	Qy.	Rate.	Cost		Qy	Cost
Shifting the tiles.			52 65	4 8.	236	4 9	52 65	236 4 9
Putting zinc plate for Valleys			70	12.	52	8 -	70	52 8.
Putting Ventilators in Store			6.	8.	7	. .	6	7 -
Putting Teak wire door Shutters			32½	. .	32	8 -	32½	32 8.
Putting Honney wood window Shutters			34½	12	25	4 .	34½	25 4.
Jungle wood doors			52½	- 8.	26	4 .	52½	26 4.
Teak wood work for roofing			3	3. 8.	10	8 .	8	10 8.
Honney — do —			16	2 . .	32	. .	16	32 . .
Iron bars for the bath room			50½	- 2.	6	5 .	50½	6 5 .
Constructing brick do Chunam wall for bathroom			78	- 3 -	14	10	78	14 10 -
Roofing with zinc plate for			60 9/16	- 6 -	22	126	60 9/16	22 126
Chunam plastering bath room			1·32	2 8.	3	49	1·32	3 49
Constructing parapet wall for the Stables			220	- 16	20	1 .	220	20 1
Chunam plastering - do			2·52	2 8.	6	49	2·52	6 9
- Gravel flooring for Stables			8·83	1 - .	8	18 3	8·83	8 13 3
Concrete flooring for the drawing room			2·30	2 8.	5	1 .	2·30	5 12.
Putting stone flake for water closet			39 9/16	- 3 -	7	7 3	39 9/16	7 3
Putting eve for Verandah			54	- 2 .	6	12 .	54	6 1.
Wood oiling			·71	5 . .	3	7	·71	3 9
Constructing a small Verandah in the rear kitchen			.	. 8.	5	8 0	11	5

Repairing the Bath Room wall with plastering	19¾		3	3	11	3	19¾	3	11	3		
Coping for the front Verandah	128		16	12			128	12				
Petty Repairs												
Putting stove bends in stove	2	5		10			2	10				
Keeping lamps in the office	1	3	8	3	8		1	3	8			
do Lamp host with Lantern	1	5		5			1	5				
Cooly for putting old beams	4	1		4			4	4				
Clearing the Site	Lump Sum							4				
Repairing the cracks	3	1	8	4	8		3	4	8			
White washing	96-21		4	26	0	9	96-21	24	0	9		

Total value of work done up to end of 189 — 608 1

Deduct previous payment made — 608 1

Net amount to be paid

Certified the above measurements have been made by me and that the work has been satisfactorily executed

Balakrishna
In charge of t

P. W. 101]

Division

Sub-Division

Name of Work: Repairs to Court House at Chittoor

Name of Contractor Chenna Venkaya Pantulu

Date of Measurement 1-10-1895

Date of payment

Memo of Payments
(To be filled in Office of Payments)

Arrears brought forward

Work done as per this Bill

Total

Payment now made

Balance due

Read:-

Govt. Rso No. 390-1 Muz:7 24-95 Dy 10th Sepr/95 Sanctioning an estimate amounting to Rs 682/- for repairing the Govt. annal Chattram at Bidadi.

Report Dy 16th May/96 from the overseer, Muz: Dept Submitting a completion bill for Rs 608-1-0 being the actual cost incurred in repairing the above Chattram.

———·———

No. 1205-6 Muz 7 24-95 Dy 5/6/96 Order thereon:-

The completion bill for Rs 608-1-0 is countersigned and forwarded to the Compr for audit and payment in the Bangalore Distt Treasury from the Sum of Rs 717-3-5 deposited in the Savings Bank to the credit of the Chattram as directed in

the Govt Bro read above

Secy

To The Dy Comr Bangalore Distt
" Comptr to Govt,
with the completion bill.

I. P. No. 6612

OFFICE OF THE COMPTROLLER, MYSORE GOVT.

Bangalore, 13th June 1896.

From

E. R. SUBRAYER, Rsq.,

Comptroller, Mysore Govt.

To

The Secretary to the Govt. of Mysore,

Muzrai Dept.

Sir,

In returning herewith the Completion bill for Rs 608-1-" received with Pro. No. 1205-6 Muz. dated 5th June 1896, I have the honor to point out that the total of the bill according to calculation amounts to Rs 603-1-" and not Rs 608-1-" as shown therein, and to request that you will be so good as to recounter-sign the bill for the correct amount and return to this office for audit.

I have the honor to be

Sir

Your most obedient Servant

E R Subrayer

Comptroller.

Mysore Govt.

ERS



From

The Comptroller, Mysore Govt.

To

The Secretary to the Govt. of Mysore

_____ *Dept.*

Dated

Despatched

Received 15/6

L. F. No.

No.

SUBJECT MATTER.

Gen. Serial No. 30.]

189

MUZARAL.

From

To

The Comptroller & Govt

Dated 15th June 1896

Despatched

Received

Enclosures No. 1 A B

General No. 1249 + 1250
Muzaral F. No. 24-95 24-95

His No 66127.
13th June 96 returning
the Completion Bill
Countersigned under
Govt Pro 1208-6
Muz 724-95
of 15th Instant for
Correction of Total
the amount of the Bill
of Total from Rs 608-1-0
to Rs 603-1-0

Has the honor

~~Sent~~ herewith.
Return the
Completion Bill
in quertain duly
Corrected and Countersigned
for Rs 603-1-0.

By order

Asst
Asst-Secy

No 1250 Genl 24-95 AMG

Copy to Dy Cons. Bangalore Dn
for information

By O

Asst
Asst-Secy

AMG

ఫిర్యాదుదారు నుండి స్వీకరించిన ఆధారములు

ఫిర్యాదు నమోదు చేయుటకు ఇచ్చిన రసీదు

ఫిర్యాదు నమోదు చేసిన పోలీసు అధికారి యొక్క

వివరములు మరియు ఫిర్యాదు నమోదు చేసిన

పోలీసు అధికారి సంతకము.

ఫిర్యాదు యొక్క సారాంశము మరియు

నేరము జరిగిన ప్రదేశము మరియు సంఘటన

కాలము తెలుపుతూ ఫిర్యాదుదారు సంతకము

లేదా వేలిముద్ర మరియు ఫిర్యాదు నమోదు

అధికారి సంతకము 603-1-ఆ రికార్డులు

మరియు ఫిర్యాదుదారుల వివరాలు

మరియు ఫిర్యాదు ఇచ్చిన వారికి తిరిగి

ఇచ్చుటకు ఫిర్యాదులో ఉన్న వివరాలు

ఆధారంగా ఫిర్యాదుదారుని సంప్రదించుటకు

అనువుగా ఫిర్యాదులో ఫోన్ నెంబర్లు

వివరములు

2.7.96

ఫిర్యాదు స్వీకరించిన పోలీసు అధికారి

సంతకము